



Applies To: 1999-02 Odyssey – ALL without Navigation System  
1998-02 Accord – ALL

February 12, 2002

## Clock Light Does Not Work (Supersedes 01-097, dated November 6, 2001)

### PROBLEM

The clock does not light up with the other instrument panel lights.

### CORRECTIVE ACTION

Replace the clock illumination bulb.

### PARTS INFORMATION

- Clock Bulb: P/N 35505-S84-B02, H/C 5435540

### WARRANTY CLAIM INFORMATION

**In warranty:** The normal warranty applies.

Operation Number: 715106

Flat Rate Time: 0.3 hour for Odyssey  
0.2 hour for Accord

Failed Part: P/N 35505-S84-N01  
H/C 5435557

Defect Code: 032

Contention Code: B01


Template ID: 01-097A for Odyssey  
01-097B for Accord

Skill Level: Repair Technician

**Out of warranty:** Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

### REPAIR PROCEDURE

1. *Odyssey:* Remove the instrument panel (see page 20-68 in the service manual). *Accord:* Remove the clock from the center panel (see page 22-129 in the service manual).
2. Replace the clock illumination bulb.



3. Reinstall the clock or the instrument panel.
4. Set the clock.

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.